

Désignation	Dimensions dxDxB(mm)	Masse (kg)
51100	10x24x9	0.02
51101	12x26x9	0.02
51102	15x28x9	0.02
51103	17x30x9	0.03
51104	20x35x10	0.04
51105	25x42x11	0.06
51106	30x47x11	0.06
51107	35x52x12	0.08
51108	40x60x13	0.12
51109	45x65x14	0.14
51110	50x70x14	0.16
51111	55x78x16	0.23
51112	60x85x17	0.2
51113	65x90x18	0.33
51114	70x95x18	0.35
51115	75x100x19	0.4
51116	85x110x19	0.44
51117	80x105x19	0.42
51118	90x120x22	0.67
51120	100x135x25	0.97
51122	110x145x25	1.05
51124	120x155x30	1.15
51126	130x170x30	1.85
51128	140x180x31	2.05
51130	150x190x31	2.2
51132	160x200x31	2.35
51134	170x215x34	3.3
51200	10x26x11	0.03
51201	12x28x11	0.03
51202	15x32x12	0.05
51203	17x35x12	0.05
51204	20x40x14	0.08
51205	25x47x15	0.11
51206	30x52x16	0.13
51207	35x62x18	0.22
51208	40x68x19	0.28
51209	45x73x20	0.3
51210	50x78x22	0.37
51211	55x90x25	0.59
51212	60x95x26	0.65
51213	65x100x27	0.78
51214	70x100x27	0.79
51215	75x105x27	0.83
51216	80x115x28	0.91
51217	85x125x31	1.2
51218	90x135x35	1.7
51220	100x150x38	2.2
51222	110x160x38	2.4
51224	120x170x39	2.65
51226	130x190x45	4
51228	140x200x46	4.35
51230	150x215x50	6.1
51232	160x225x51	6.55